

SERVICE BULLETIN

Document No. 159-012-00, Rev. 0 November 10, 2003

ONBOARD SYSTEMS INTERNATIONAL

13915 NW 3rd Court Vancouver, WA 98685 USA

Phone: 360-546-3072 Fax: 360-546-3073 Toll Free: 800-275-0883

www.OnboardSystems.com

Subject: Cargo Hook enhanced safety.

Helicopters Affected: Robinson R22 and R44 aircraft with 12 volt electrical systems and an Onboard Systems 3.5K Keeperless Hook, part number 528-023-00, installed.

Compliance: Optional

Description:

The cargo hook, based on reports from the field, has exhibited inconsistent relatching of its internal release mechanism. The problems have been traced to an internal spring, which is used to retract the release mechanism and manual release cable after a load is released. Upon further investigation it has been concluded that due to manufacturing inconsistencies some of the springs do not provide an adequate retract force or have a tendency to work their way out of their optimal operating position. In the event of this occurrence, the result may be an incomplete locking of the mechanism. This could lead to an inadvertent load release.

This service bulletin contains instructions for replacing the existing spring with a new spring and spring retainer. The new spring is of a design that provides a higher retract force. The spring retainer ensures that the spring is maintained in its proper position.

The actions required by this service bulletin are described below.

Approval: The engineering design aspects of this bulletin are FAA/DER approved.

Manpower: Replacement of the spring will require 1.0 man-hours. Man-hours are based on hands-on time and may vary with personnel and facilities available. No machining operations are required. Installation consists of removing and replacing parts and re-identifying the cargo hook as a 528-023-03.





Flow Monitoring Systems



Customer Directed Development

Required Material: The following material is required for accomplishment of this bulletin and may be obtained from Onboard Systems:

Qty 1 P/N 514-057-00 Spring

Qty 1 P/N 290-819-00 Spring Retainer

Qty 2 P/N 510-115-00 Cotter Pin

.032" Lockwire

Special Tools: Not required

Weight and Balance: Not affected


Electrical Load Data: Not affected


Publications Affected: None


Accomplishment Instructions:


To be accomplished within 60 days of the release of this service bulletin.

Remove existing spring and replace with spring and retainer per included instructions beginning at step one.









Step 13

Fasten solenoid assembly onto side plate with washers, nut, and cotter pin.

Torque first nut to 15 in-lbs. and rotate to next castellation to insert cotter pin.

Torque second nut to 20-25 in-lbs.




Step 14

Re-identify the cargo hook as P/N 528-023-03 by steel stamping a "3" over the last 0 in the P/N on the identification plate located on the outside of the solenoid assembly.



Reinstall Cargo Hook on aircraft per hook Owner's Manual instruction or ICA.

Place the cable into the fork on the manual release lever as illustrated. Verify correct setting per the following. Move the manual release lever in the clockwise direction until free play is removed. Measure the cable ball end free play with the manual release handle in the cockpit in the non-release position. The gap should measure approximately 1/8".



Record compliance with this service bulletin in the aircraft logbook as appropriate.