

2020 Repair Department Pricing

- ▶ All prices in US Dollars
- ▶ Prices effective through December 31, 2020
- ▶ Prices subject to change without notice
- ▶ Definitions:
 - ▶ ATP: Perform Acceptance Test Procedure (ATP) as outlined in applicable Onboard Systems service or component maintenance manual.
 - ▶ Inspection: Product disassembly, visual inspection, lubricate, reassembly and ATP. Recommended for customers with contracts that require periodic cargo hook inspection (such as USFS contracts, etc.)
 - ▶ Overhaul: Perform overhaul as outlined in applicable Onboard Systems service or component maintenance manual.
- ▶ Payment: Orders for repair department services that have established fixed pricing require the receipt of payment, with the exception of customers with net terms, before the commencement of any services.
- ▶ The quoted price is limited to and only covers the parts and labor for the basic service as outlined in the applicable Onboard Systems document. Any additional parts or labor needed to complete the service will be priced over and above the quoted price. The price for an exchange will be based on the quoted price plus any over and above findings or discrepancies.

Repair and Overhaul Pricing

Part Number	Description	ATP	Inspection	Overhaul	Price for New
Belly Cargo Hooks					
528-002-XX	6,000 LB Cargo Hook	\$220 USD	\$550 USD	\$4,191 USD	N/A
528-010-XX	TALON® LC Cargo Hook	\$154 USD	\$385 USD	\$1,155 USD	\$5,753 USD
528-017-XX	TALON Big Mouth Cargo Hook	\$154 USD	\$385 USD	\$1,265 USD	N/A
528-020-XX	TALON MC Cargo Hook	\$154 USD	\$385 USD	\$1,276 USD	\$9,207 USD
528-023-XX	TALON LC Keeperless Cargo Hook	\$154 USD	\$385 USD	\$1,100 USD	\$6,078 USD
528-028-XX	TALON LC Hydraulic Cargo Hook	\$154 USD	\$385 USD	\$1,238 USD	\$6,391 USD
528-029-XX	TALON LC Keeperless Cargo Hook	\$154 USD	\$385 USD	\$1,238 USD	\$6,237 USD
Remote Equipment					
210-242-00	2K Remote Hook (Gen 1)	\$198 USD	\$429 USD	\$957 USD	N/A
210-303-00	2K Remote Hook (Gen 2)	\$198 USD	\$429 USD	\$957 USD	\$2,598 USD
528-018-XX	3.3K Remote Hook	\$198 USD	\$429 USD	\$996 USD	\$2,887 USD
528-019-XX	6K Remote Hook	\$198 USD	\$429 USD	\$1,029 USD	\$4,024 USD
528-021-XX	2K Carousel Hook	\$154 USD	\$308 USD	\$792 USD	\$2,250 USD
210-253-00	Crew-Loc Hook Half-Cage	\$154 USD	\$308 USD	\$502 USD	\$1,768 USD
210-254-00	Crew-Loc Hook Full-Cage (Gen 1)	\$154 USD	\$308 USD	\$502 USD	\$1,768 USD
210-302-00	Crew-Loc Hook Full-Cage (Gen 2)	\$154 USD	\$314 USD	\$501 USD	\$1,725 USD

2020 Repair Department Pricing

Repair and Overhaul Pricing

Part Number	Description	ATP	Inspection	Overhaul	Price for New
232-457-XX	Electric Swivel Assembly	N/A	N/A	\$523 USD	\$2,153 USD
528-046-00	Hayabusa® 6K Remote Hook	N/A	N/A	\$1,507 USD	\$11,338 USD
528-045-00	Hayabusa® 10K Remote Hook	N/A	N/A	\$1,507 USD	\$14,107 USD
Hook Kits					
210-201-03	Airbus AS350 Swing Removable Provisions*	N/A	N/A	\$3,031 USD	\$28,449 USD
200-088-03	Bell 204-412 System	\$369 USD	N/A	\$8,602 USD	\$25,870 USD
200-088-10	Bell 204-412 System	\$303 USD	N/A	\$5,687 USD	\$25,870 USD
200-089-03	Bell 204-412 System w/Load Cell	\$600 USD	N/A	\$9,235 USD	\$28,350 USD
200-089-11	Bell 204-412 System w/Load Cell	\$413 USD	N/A	\$6,320 USD	\$28,350 USD
200-089-22	Bell 204-412 System w/ OWS	\$534 USD	N/A	\$6,320 USD	\$31,260 USD
200-258-XX	Bell 206L/407 Cargo Hook Kit*	N/A	N/A	\$2,640 USD	\$23,357 USD
200-259-XX	Bell 206L/407 Cargo Hook Kit w/ OWS*	N/A	N/A	\$3,108 USD	\$30,062 USD
200-268-XX	Bell 206 A&B Cargo Hook Kit*	N/A	N/A	\$3,113 USD	\$18,780 USD
200-269-XX	Bell 206 A&B Cargo Hook Kit w/OWS*	N/A	N/A	\$3,823 USD	\$26,213 USD
200-329-00	Bell 407 Fixed Suspension System*	N/A	N/A	\$2,338 USD	\$23,358 USD
200-391-XX	Bell 204-412 Non-Rotating w/ OWS	\$308 USD	N/A	\$4,312 USD	N/A
200-401-XX	Bell 204-412 Non-Rotating System	\$308 USD	N/A	\$3,696 USD	N/A
210-164-00	Bell 206B Adaptor Link Assembly	N/A	N/A	\$204 USD	\$717 USD
232-289-00	Leonardo A109 Suspension System	N/A	N/A	\$3,113 USD	N/A
232-449-01	MD500 Attach Point Assembly	N/A	N/A	\$204 USD	\$2,639 USD
232-292-01	R44 Suspension Assembly	N/A	N/A	\$204 USD	\$2,370 USD
Onboard Weighing Systems**					
Misc.	Link Load Cell	\$176 USD	\$902 USD	N/A	Varies
Misc.	Pin Load Cell	\$176 USD	\$902 USD	N/A	Varies
Misc.	Shear Beam Load Cell	\$209 USD	\$1,513 USD	N/A	Varies
Misc.	Tubular Load Cell	\$209 USD	\$2,079 USD	N/A	Varies
210-095-XX	C-39 Cockpit Indicator	\$176 USD	N/A	N/A	Varies
Shop Labor Rate					
Misc.	Shop Labor Rate (per hour)				\$120 USD

* This service includes a system inspection and a cargo hook overhaul.

** If the load cell is not repairable, Onboard offers a \$500 credit toward the the purchase of new load cell.

2020 Repair Department Pricing

Upgrade Pricing

Part Number	Description	Parts Only	Parts + Factory Installation	Parts + Factory Overhaul (Free Upgrade Installation)
232-613-00	Bell 204-412 Cargo Hook Release Lever Upgrade Kit	\$1,247 USD	\$1,282 USD	\$2,431 USD
232-076-03	Bell 204-412 Surefire Upgrade (Hook 528-020-XX)	\$1,089 USD	\$1,281 USD	\$2,415 USD
232-186-01	TALON LC Hydraulic Cargo Hook Surefire Upgrade (Hook 528-28-XX)	\$522 USD	\$699 USD	\$1,733 USD
232-212-05	TALON LC Keeperless Cargo Hook Surefire Upgrade (Hook 528-029-XX)	\$522 USD	\$699 USD	\$1,733 USD

Service Bulletin Compliance Pricing

Document Number	Description	Required Part Numbers	Parts	Labor	Total
159-001-00	TALON LC Hook Drain Holes		N/A	\$121 USD	\$121 USD
159-002-00	Bell 204-412 Suspension Load Link	232-009-01	\$1,942 USD	\$66 USD	\$2,008 USD
159-003-00	TALON MC Hook Load Ring Decal	215-096-01	\$22 USD	N/A	\$22 USD
159-004-00	E-72 Release Cable	268-004-01, 270-085-00	\$985 USD	N/A	\$985 USD
159-005-02	TALON MC Hook Spring	650-069-00	\$22 USD	\$121 USD	\$143 USD
159-006-00	Analog Slave Meter Installation		N/A	N/A	N/A
159-007-00	TALON LC Hook Side Plates	232-026-02	\$2,838 USD	\$182 USD	\$3,020 USD
159-009-00	Superseded by 159-020-00		N/A	N/A	N/A
159-010-00	TALON MC Keeperless Hook Release Lever		\$594 USD	\$182 USD	\$776 USD
159-011-00	TALON LC Keeperless Hook Spring		\$99 USD	\$121 USD	\$220 USD
159-012-00	TALON LC Keeperless Hook Spring	514-057-00, 290-819-00, 510-115-00	\$253 USD	\$120 USD	\$374 USD
159-013-00	AS350 Swing Frame		N/A	N/A	N/A
159-014-00	AS350 Swing Frame	210-218-00	\$9,834 USD	N/A	\$9,834 USD
159-015-00	R22/R44 Cargo Hook Gimbal		N/A	N/A	N/A
159-016-00	Superseded by 159-023-00		N/A	N/A	N/A
159-017-00	TALON LC Hook Toggle	232-028-01, 290-306-01, 290-304-01	\$1,826 USD	\$237 USD	\$2,063 USD
159-018-00	TALON LC Big Mouth Release Knob	290-471-02, 510-271-00, 510-246-00	\$204 USD	\$66 USD	\$270 USD



2020 Repair Department Pricing

Service Bulletin Compliance Pricing

Document Number	Description	Required Part Numbers	Parts	Labor	Total
159-019-00	TALON LC Hook Toggle	232-028-01, 290-306-01, 290-304-01	\$556 USD	\$237 USD	\$792 USD
159-020-00	Bell 206L/407 Pillow Blocks	232-030-02: Qty 2	\$2,888 USD	N/A	\$2,888 USD
159-021-00	AS350B3 Collective Friction Knob	291-105-00, 290-811-01	\$407 USD	N/A	\$407 USD
159-022-00	R44 Revised Maintenance Criteria		N/A	N/A	N/A
159-023-00	R44 Cargo Hook Suspension	232-292-01	\$1,689 USD	N/A	\$1,689 USD
159-024-00	TALON 3K Remote Hook Keeper Bolt	510-714-00, 510-239-00, 510-370-00, 514-014-00, 510-715-00, 291-277-00	\$72 USD	\$182 USD	\$253 USD
159-025-00	TALON LC Keeperless Hook Locked Indication		N/A	N/A	N/A
159-026-00	TALON LC Keeperless Hook Release Cover	P/N 290-898-01	\$435 USD	\$33 USD	\$468 USD
159-027-00	TALON Keeperless Hook Rigging		N/A	N/A	N/A
159-028-00	R22/R44 12VDC Upgrade	455-007-00, 340-035-00, 215-181-00, 514-056-00	\$413 USD	\$121 USD	\$534 USD
159-029-00	TALON 3K Remote Hook Load Ring Size	215-203-00	\$17 USD	N/A	\$17 USD
159-030-00	Bell 206L/407 Manual Release Cable	268-004-01	\$732 USD	N/A	\$732 USD
159-033-00	Electric Swivel Operation	No labor charge for service	N/A	\$0	\$0
159-034-00	Fuel Drain Guard	290-899-01 & 610-024-00	\$462 USD	N/A	\$462 USD
159-036-00	Load Cell Torsion	See Service Bulletin	\$1,100 USD off list price	N/A	\$1,100 USD off list price
159-038-00	Hayabusa Hook Keeper Lock	291-722-01	N/A	N/A	N/A
159-039-00	AS350 Replacement Cargo Hook Kit manual release cable and bumper upgrade	268-024-02, 232-155-00	\$2,607 USD	N/A	\$2,607 USD
159-041-00	Non-Rotating Cargo Hook Suspension System Interference for Bell 412EP, 412HP, and 412SP		N/A	N/A	N/A
159-042-00	Load rating increase for TALON 3K Remote Cargo Hook series	200-444-00	\$32 USD	\$56 USD	\$88 USD