

## 2023 Repair Department Pricing

- ▶ All prices in US Dollars
- ▶ Prices effective through December 31, 2023
- ▶ Prices subject to change without notice
- ▶ Definitions:
  - ▶ ATP: Perform Acceptance Test Procedure (ATP) as outlined in applicable Onboard Systems service or component maintenance manual.
  - ▶ Inspection: Product disassembly, visual inspection, lubricate, reassembly and ATP. Recommended for customers with contracts that require periodic cargo hook inspection (such as USFS contracts, etc.)
  - ▶ Overhaul: Perform overhaul as outlined in applicable Onboard Systems service or component maintenance manual.
- ▶ Payment: Orders for repair department services that have established fixed pricing require the receipt of payment, with the exception of customers with net terms, before the commencement of any services.
- ▶ The quoted price is limited to and only covers the parts and labor for the basic service as outlined in the applicable Onboard Systems document. Any additional parts or labor needed to complete the service will be priced over and above the quoted price. The price for an exchange will be based on the quoted price plus any over and above findings or discrepancies.

### Repair and Overhaul Pricing

Part Number	Description	ATP	Inspection	Overhaul	Price for New
<b>Belly Cargo Hooks</b>					
528-002-XX	6,000 LB Cargo Hook	\$323 USD	\$806 USD	\$9,574 USD	N/A
528-010-XX	TALON® LC Cargo Hook	\$227 USD	\$565 USD	\$1,692 USD	\$7,580 USD
528-017-XX	TALON Big Mouth Cargo Hook	\$227 USD	\$565 USD	\$1,852 USD	N/A
528-020-XX	TALON MC Cargo Hook	\$227 USD	\$565 USD	\$1,869 USD	\$11,107 USD
528-023-XX	TALON LC Keeperless Cargo Hook	\$227 USD	\$565 USD	\$2,622 USD	\$8,009 USD
528-028-XX	TALON LC Hydraulic Cargo Hook	\$227 USD	\$565 USD	\$2,935 USD	\$8,421 USD
528-029-XX	TALON LC Keeperless Cargo Hook	\$227 USD	\$565 USD	\$2,935 USD	\$8,218 USD
<b>Remote Equipment</b>					
210-242-00	2K Remote Hook (Gen 1)	\$290 USD	\$629 USD	\$1,727 USD	N/A
210-303-00	2K Remote Hook (Gen 2)	\$290 USD	\$629 USD	\$1,402 USD	\$3,249 USD
528-018-XX	3.3K Remote Hook	\$290 USD	\$629 USD	\$1,783 USD	\$3,609 USD
528-019-XX	6K Remote Hook	\$290 USD	\$629 USD	\$1,832 USD	\$5,030 USD
528-021-XX	2K Carousel Hook	\$227 USD	\$452 USD	\$1,160 USD	\$2,813 USD
210-253-00	Crew-Loc Hook Half-Cage	\$227 USD	\$452 USD	\$736 USD	\$1,803 USD
210-254-00	Crew-Loc Hook Full-Cage (Gen 1)	\$227 USD	\$452 USD	\$736 USD	\$1,803 USD
210-302-00	Crew-Loc Hook Full-Cage (Gen 2)	\$227 USD	\$460 USD	\$735 USD	\$2,204 USD
210-305-XX	Electric Swivel Assembly	N/A	N/A	\$767 USD	\$2,006 USD

# 2023 Repair Department Pricing

## Repair and Overhaul Pricing

Part Number	Description	ATP	Inspection	Overhaul	Price for New
528-046-00	Hayabusa® 6K Remote Hook	N/A	N/A	\$3,276 USD	\$15,483 USD
528-045-00	Hayabusa® 10K Remote Hook	N/A	N/A	\$3,276 USD	\$19,264 USD
<b>Hook Kits</b>					
210-201-03	Airbus AS350 Swing Removable Provisions*	N/A	N/A	\$4,438 USD	\$37,134 USD
200-088-03	Bell 204-412 System	\$541 USD	N/A	\$12,596 USD	\$30,917 USD
200-088-10	Bell 204-412 System	\$444 USD	N/A	\$8,327 USD	\$30,917 USD
200-089-03	Bell 204-412 System w/Load Cell	\$878 USD	N/A	\$13,523 USD	\$33,880 USD
200-089-11	Bell 204-412 System w/Load Cell	\$606 USD	N/A	\$9,254 USD	\$33,880 USD
200-089-22	Bell 204-412 System w/ OWS	\$783 USD	N/A	\$9,254 USD	\$37,358 USD
200-258-XX	Bell 206L/407 Cargo Hook Kit*	N/A	N/A	\$4,988 USD	\$30,488 USD
200-259-XX	Bell 206L/407 Cargo Hook Kit w/ OWS*	N/A	N/A	\$5,673 USD	\$39,240 USD
200-268-XX	Bell 206 A&B Cargo Hook Kit*	N/A	N/A	\$4,558 USD	\$26,848 USD
200-269-XX	Bell 206 A&B Cargo Hook Kit w/OWS*	N/A	N/A	\$5,598 USD	\$37,474 USD
200-329-00	Bell 407 Fixed Suspension System*	N/A	N/A	\$4,546 USD	\$30,062 USD
210-164-00	Bell 206B Adaptor Link Assembly	N/A	N/A	\$299 USD	\$945 USD
232-289-00	Leonardo A109 Suspension System	N/A	N/A	\$5,680 USD	N/A
232-449-01	MD500 Attach Point Assembly	N/A	N/A	\$299 USD	\$3,476 USD
232-292-01	R44 Suspension Assembly	N/A	N/A	\$299 USD	\$3,928 USD
<b>Onboard Weighing Systems**</b>					
Misc.	Link Load Cell	\$304 USD	\$1,555 USD	N/A	Varies
Misc.	Pin Load Cell	\$304 USD	\$1,555 USD	N/A	Varies
Misc.	Shear Beam Load Cell	\$361 USD	\$2,607 USD	N/A	Varies
Misc.	Tubular Load Cell	\$361 USD	\$3,582 USD	N/A	Varies
210-095-XX	C-39 Cockpit Indicator	\$304 USD	N/A	N/A	Varies

\* This service includes a system inspection and a cargo hook overhaul.  
 \*\* If the load cell is not repairable, Onboard offers a \$500 credit toward the the purchase of new load cell.

# 2023 Repair Department Pricing

Upgrade Pricing				
Part Number	Description	Parts Only	Parts + Factory Installation	Parts + Factory Overhaul (Free Upgrade Installation)
232-613-00	Bell 204-412 Cargo Hook Release Lever Upgrade Kit	\$2,007 USD	\$2,294 USD	\$3,698 USD
232-076-03	Bell 204-412 Surefire Upgrade (Hook 528-020-XX)	\$1,806 USD	\$2,011 USD	\$3,536 USD
232-186-01	TALON LC Hydraulic Cargo Hook Surefire Upgrade (Hook 528-28-XX)	\$1,213 USD	\$1,418 USD	\$4,148 USD
232-212-05	TALON LC Keeperless Cargo Hook Surefire Upgrade (Hook 528-029-XX)	\$1,213 USD	\$1,418 USD	\$4,148 USD

Service Bulletin Compliance Pricing					
Document Number	Description	Required Part Numbers	Parts	Labor	Total
159-001-00	TALON LC Hook Drain Holes		N/A	\$205 USD	\$205 USD
159-002-00	Bell 204-412 Suspension Load Link	232-009-01	\$2,844 USD	\$205 USD	\$3,049 USD
159-003-00	TALON MC Hook Load Ring Decal	215-096-01	\$42 USD	N/A	\$42 USD
159-004-00	E-72 Release Cable	268-004-01, 270-085-00	\$1,443 USD	N/A	\$1,443 USD
159-005-02	TALON MC Hook Spring	650-069-00	\$42 USD	\$205 USD	\$247 USD
159-007-00	TALON LC Hook Side Plates	232-026-02	\$4,156 USD	\$266 USD	\$4,422 USD
159-010-00	TALON MC Keeperless Hook Release Lever		\$871 USD	\$266 USD	\$1,137 USD
159-011-00	TALON LC Keeperless Hook Spring		\$145 USD	\$205 USD	\$350 USD
159-012-00	TALON LC Keeperless Hook Spring	514-057-00, 290-819-00, 510-115-00	\$371 USD	\$205 USD	\$576 USD
159-014-00	AS350 Swing Frame	210-218-00	\$14,399 USD	N/A	\$14,399 USD
159-017-00	TALON LC Hook Toggle	232-028-01, 290-306-01, 290-304-01	\$2,674 USD	\$348 USD	\$3,021 USD
159-018-00	TALON LC Big Mouth Release Knob	290-471-02, 510-271-00, 510-246-00	\$299 USD	\$205 USD	\$504 USD
159-019-00	TALON LC Hook Toggle	232-028-01, 290-306-01, 290-304-01	\$815 USD	\$348 USD	\$1,160 USD
159-020-00	Bell 206L/407 Pillow Blocks	232-030-02: Qty 2	\$4,230 USD	N/A	\$4,230 USD
159-021-00	AS350B3 Collective Friction Knob	291-105-00, 290-811-01	\$597 USD	N/A	\$597 USD
159-023-00	R44 Cargo Hook Suspension	232-292-01	\$2,474 USD	N/A	\$2,474 USD

## 2023 Repair Department Pricing

### Service Bulletin Compliance Pricing

Document Number	Description	Required Part Numbers	Parts	Labor	Total
159-024-00	TALON 3K Remote Hook Keeper Bolt	510-714-00, 510-239-00, 510-370-00, 514-014-00, 510-715-00, 291-277-00	\$134 USD	\$266 USD	\$371 USD
159-026-00	TALON LC Keeperless Hook Release Cover	P/N 290-898-01	\$639 USD	\$205 USD	\$844 USD
159-028-00	R22/R44 12VDC Upgrade	455-007-00, 340-035-00, 215-181-00, 514-056-00	\$606 USD	\$205 USD	\$811 USD
159-029-00	TALON 3K Remote Hook Load Ring Size	215-203-00	\$33 USD	N/A	\$33 USD
159-030-00	Bell 206L/407 Manual Release Cable	268-004-01	\$1,072 USD	N/A	\$1,072 USD
159-034-00	Fuel Drain Guard	290-899-01 & 610-024-00	\$676 USD	N/A	\$676 USD
159-036-00	Load Cell Torsion	See Service Bulletin	\$1,611 USD off list price	N/A	\$1,611 USD off list price
159-039-00	AS350 Replacement Cargo Hook Kit manual release cable and bumper upgrade	268-024-02, 232-155-00	\$3,818 USD	N/A	\$3,818 USD
159-042-00	Load rating increase for TALON 3K Remote Cargo Hook series	200-444-00	\$49 USD	\$205 USD	\$205 USD