

2018 Repair Department Pricing

- ▶ All prices in US Dollars
- ▶ Prices effective through December 31, 2018
- ▶ Prices subject to change without notice
- ▶ Definitions:
 - ▶ ATP: Perform Acceptance Test Procedure (ATP) as outlined in applicable Onboard Systems service or component maintenance manual.
 - ▶ Inspection: Product disassembly, visual inspection, lubricate, reassembly and ATP. Recommended for customers with contracts that require periodic cargo hook inspection (such as USFS contracts, etc.)
 - ▶ Overhaul: Perform overhaul as outlined in applicable Onboard Systems service or component maintenance manual.
- ▶ Payment: Orders for repair department services that have established fixed pricing require the receipt of payment, with the exception of customers with net terms, before the commencement of any services.
- ▶ The quoted price is limited to and only covers the parts and labor for the basic service as outlined in the applicable Onboard Systems document. Any additional parts or labor needed to complete the service will be priced over and above the quoted price. The price for an exchange will be based on the quoted price plus any over and above findings or discrepancies.

Repair and Overhaul Pricing

Part Number	Description	ATP	Inspection	Overhaul	Price for New
Belly Cargo Hooks					
528-002-XX	6,000 LB Cargo Hook	\$175 USD	\$450 USD	\$2,870 USD	N/A
528-010-XX	TALON® LC Cargo Hook	\$135 USD	\$335 USD	\$1,000 USD	\$4,980 USD
528-017-XX	TALON Big Mouth Cargo Hook	\$135 USD	\$335 USD	\$1,095 USD	\$5,080 USD
528-020-XX	TALON MC Cargo Hook	\$135 USD	\$335 USD	\$1,105 USD	\$7,970 USD
528-023-XX	TALON LC Keeperless Cargo Hook	\$135 USD	\$335 USD	\$955 USD	\$5,260 USD
528-028-XX	TALON LC Hydraulic Cargo Hook	\$135 USD	\$335 USD	\$1,075 USD	\$5,535 USD
528-029-XX	TALON LC Keeperless Cargo Hook	\$135 USD	\$335 USD	\$1,075 USD	\$5,400 USD
Remote Equipment					
210-242-00	2K Remote Hook	\$175 USD	\$375 USD	\$830 USD	\$2,374 USD
210-303-00	2K Remote Hook	\$175 USD	\$375 USD	\$830 USD	\$2,425 USD
528-018-XX	3K Remote Hook	\$175 USD	\$375 USD	\$865 USD	\$2,775 USD
528-019-XX	6K Remote Hook	\$175 USD	\$375 USD	\$895 USD	\$3,870 USD
528-021-XX	2K Carousel Hook	\$135 USD	\$270 USD	\$690 USD	\$2,310 USD
210-253-00	Crew-Loc Hook Half-Cage	\$135 USD	\$270 USD	\$435 USD	\$1,565 USD
210-254-00	Crew-Loc Hook Full-Cage	\$135 USD	\$270 USD	\$435 USD	\$1,650 USD
210-302-00	Crew-Loc Hook Full-Cage	\$135 USD	\$270 USD	\$435 USD	\$1,610 USD
232-457-XX	Electrical Swivel Assembly	N/A	N/A	\$450 USD	\$1,640 USD

2018 Repair Department Pricing

Repair and Overhaul Pricing

Part Number	Description	ATP	Inspection	Overhaul	Price for New
Hook Kits					
210-201-03	Airbus A330 Swing Removable Provisions*	N/A	N/A	\$2,625 USD	\$25,560 USD
200-088-03	Bell 204-412 System	\$265 USD	N/A	\$6,690 USD	\$23,245 USD
200-088-10	Bell 204-412 System	\$265 USD	N/A	\$4,925 USD	\$23,245 USD
200-089-03	Bell 204-412 System w/Load Cell	\$465 USD	N/A	\$7,240 USD	\$23,245 USD
200-089-11	Bell 204-412 System w/Load Cell	\$360 USD	N/A	\$5,475 USD	\$25,470 USD
200-089-22	Bell 204-412 System w/ OWS	\$465 USD	N/A	\$5,475 USD	\$28,085 USD
200-258-XX	Bell 206L/407 Cargo Hook Kit*	N/A	N/A	\$2,290 USD	\$19,660 USD
200-259-XX	Bell 206L/407 Cargo Hook Kit w/ OWS*	N/A	N/A	\$2,695 USD	\$24,975 USD
200-268-XX	Bell 206 A&B Cargo Hook Kit*	N/A	N/A	\$2,695 USD	\$11,925 USD
200-269-XX	Bell 206 A&B Cargo Hook Kit w/OWS*	N/A	N/A	\$3,310 USD	\$16,645 USD
200-329-00	Bell 407 Fixed Suspension System*	N/A	N/A	\$2,025 USD	\$20,985 USD
200-391-XX	Bell 204-412 Non-Rotating w/ OWS	\$265 USD	N/A	\$3,735 USD	\$22,720 USD
200-401-XX	Bell 204-412 Non-Rotating System	\$265 USD	N/A	\$3,200 USD	\$18,290 USD
210-164-00	Bell 206B Adaptor Link Assembly	N/A	N/A	\$175 USD	\$545 USD
232-289-00	Leonardo A109 Suspension System	N/A	N/A	\$2,695 USD	N/A
232-449-01	MD500 Attach Point Assembly	N/A	N/A	\$175 USD	\$2,010 USD
232-292-01	R44 Suspension Assembly	N/A	N/A	\$175 USD	\$1,806 USD
Onboard Weighing Systems					
Misc.	Link Load Cell	\$150 USD	\$780 USD	N/A	Varies
Misc.	Pin Load Cell	\$150 USD	\$780 USD	N/A	Varies
Misc.	Shear Beam Load Cell	\$180 USD	\$1,310 USD	N/A	Varies
Misc.	Tubular Load Cell	\$180 USD	\$1,800 USD	N/A	Varies
210-095-XX	C-39 Cockpit Indicator	\$150 USD	N/A	N/A	Varies
Shop Labor Rate					
Misc.	Shop Labor Rate (per hour)				\$105 USD

* This service includes a system inspection and a cargo hook overhaul.

2018 Repair Department Pricing

Upgrade Pricing

Part Number	Description	Parts Only	Parts + Factory Installation	Parts + Factory Overhaul (Free Upgrade Installation)
232-613-00	Bell 204-412 Cargo Hook Release Lever Upgrade Kit	\$950 USD	\$1,055 USD	\$2,005 USD
232-076-03	Bell 204-412 Surefire Upgrade (Hook 528-020-XX)	\$900 USD	\$1,055 USD	\$1,995 USD
232-186-01	TALON LC Hydraulic Cargo Hook Surefire Upgrade (Hook 528-28-XX)	\$450 USD	\$605 USD	\$1,500 USD
232-212-05	TALON LC Keeperless Cargo Hook Surefire Upgrade (Hook 528-029-XX)	\$450 USD	\$605 USD	\$1,500 USD

Service Bulletin Compliance Pricing

Document Number	Description	Required Part Numbers	Parts	Labor	Total
159-001-00	Talon LC Hook Drain Holes		N/A	\$105 USD	\$105 USD
159-002-00	Bell 204-412 Suspension Load Link	232-009-01	\$1,679 USD	\$55 USD	\$1,734 USD
159-003-00	TALON MC Hook Load Ring Decal	215-096-01	\$15 USD	N/A	\$15 USD
159-004-00	E-72 Release Cable	268-004-01, 270-085-00	\$852 USD	N/A	\$852 USD
159-005-02	TALON MC Hook Spring	650-069-00	\$21 USD	\$105 USD	\$126 USD
159-006-00	Analog Slave Meter Installation		N/A	N/A	N/A
159-007-00	TALON LC Hook Side Plates	232-026-02	\$2,458 USD	\$155 USD	\$2,613 USD
159-009-00	Superseded by 159-020-00		N/A	N/A	N/A
159-010-00	TALON MC Keeperless Hook Release Lever		\$512 USD	\$155 USD	\$667 USD
159-011-00	TALON LC Keeperless Hook Spring		\$84 USD	\$105 USD	\$189 USD
159-012-00	TALON LC Keeperless Hook Spring	514-057-00, 290-819-00, 510-115-00	\$217 USD	\$105 USD	\$322 USD
159-013-00	AS350 Swing Frame		N/A	N/A	N/A
159-014-00	AS350 Swing Frame	210-218-00	\$8,515 USD	N/A	\$8,515 USD
159-015-00	R22/R44 Cargo Hook Gimbal		N/A	N/A	N/A
159-016-00	Superseded by 159-023-00		N/A	N/A	N/A
159-017-00	TALON LC Hook Toggle	232-028-01, 290-306-01, 290-304-01	\$1,579 USD	\$205 USD	\$1,784 USD
159-018-00	TALON LC Big Mouth Release Knob	290-471-02, 510-271-00, 510-246-00	\$175 USD	\$55 USD	\$230 USD

2018 Repair Department Pricing

Service Bulletin Compliance Pricing

Document Number	Description	Required Part Numbers	Parts	Labor	Total
159-019-00	TALON LC Hook Toggle	232-028-01, 290-306-01, 290-304-01	\$479 USD	\$205 USD	\$684 USD
159-020-00	Bell 206L/407 Pillow Blocks	232-030-02: Qty 2	\$2,502 USD	N/A	\$2,502 USD
159-021-00	AS350B3 Collective Friction Knob	291-105-00, 290-811-01	\$351 USD	N/A	\$351 USD
159-022-00	R44 Revised Maintenance Criteria		N/A	N/A	N/A
159-023-00	R44 Cargo Hook Suspension	232-292-01	\$1,462 USD	N/A	\$1,462 USD
159-024-00	TALON 3K Remote Hook Keeper Bolt	510-714-00, 510-239-00, 510-370-00, 514-014-00, 510-715-00, 291-277-00	\$60 USD	\$155 USD	\$215 USD
159-025-00	TALON LC Keeperless Hook Locked Indication		N/A	N/A	N/A
159-026-00	TALON LC Keeperless Hook Release Cover	P/N 290-898-01	\$376 USD	\$30 USD	\$406 USD
159-027-00	TALON Keeperless Hook Rigging		N/A	N/A	N/A
159-028-00	R22/R44 12VDC Upgrade	455-007-00, 340-035-00, 215-181-00, 514-056-00	\$356 USD	\$105 USD	\$461 USD
159-029-00	TALON 3K Remote Hook Load Ring Size	215-203-00	\$12 USD	N/A	\$12 USD
159-030-00	Bell 206L/407 Manual Release Cable	268-004-01	\$633 USD	N/A	\$633 USD
159-033-00	Electric Swivel Operation	No labor charge for service	N/A	\$0	\$0
159-034-00	Fuel Drain Guard	290-899-01 & 610-024-00	\$399 USD	N/A	\$399 USD
159-036-00	Load Cell Torsion	See Service Bulletin	\$1,000 USD off list price	N/A	\$1,000 USD off list price
159-038-00	Hayabusa Hook Keeper Lock	291-722-01	N/A	N/A	N/A
159-039-00	AS350 Replacement Cargo Hook Kit manual release cable and bumper upgrade	268-024-02, 232-155-00	\$2,258 USD	N/A	\$2,258 USD
159-041-00	Non-Rotating Cargo Hook Suspension System Interference for Bell 412EP, 412HP, and 412SP		N/A	N/A	N/A
159-042-00	Load rating increase for TALON 3K Remote Cargo Hook series	200-444-00	\$25 USD	\$50 USD	\$75 USD

Record of Revisions

Date	Revision No.	Updates
	0	Initial release
11/15/2012	1	Added 200-258-xx, 200-259-xx, 200-329-00, and removed "Internal Use Only"
1/7/2013	2	Updated pricing for 2013 & rev'd to 2
2/14/2013	3	Updated pricing, removed Exchange option, combined content in rental price list (165-005-00) into this document, and rev'd to 3
3/29/2013	4	Added SB Compliance pricing, corrected P/N in Repair/Overhaul Pricing
6/25/2013	5	Added Onboard Weighing Systems section
1/7/2015	8	Updated all for annual price change
3/10/2015	9	Added SB 159-034-00
1/2016	10	Updated all for annual price change
5/26/2016	11	Added: 159-036-00, 159-038-00, 232-457-XX, 232-289-00, 232-292-01, 210-164-00, 232-449-01, 200-391-XX, 200-401-XX
10/13/2016	12	Added new service bulletin part information, 159-039-00
1/6/2017	13	Updated all for annual price change
6/26/2017	14	Added Surefire services, plus new Crew-Loc and 2K Remote Hook services, Bell 206 A&B services, Tubular and Shear Beam load cell services, and Update Services section.
3/14/2018	15	Removed rental section, added in new parts and updated prices.