

2017 Repair Department Pricing

- ▶ All prices in US Dollars
- ▶ Prices effective through December 31, 2017
- ▶ Prices subject to change without notice
- ▶ Definitions:
 - ▶ ATP: Perform Acceptance Test Procedure (ATP) as outlined in applicable Onboard Systems service or component maintenance manual.
 - ▶ Inspection: Product disassembly, visual inspection, lubricate, reassembly and ATP. Recommended for customers with contracts that require periodic cargo hook inspection (such as USFS contracts, etc.)
 - ▶ Overhaul: Perform overhaul as outlined in applicable Onboard Systems service or component maintenance manual.
- ▶ Payment: Orders for repair department services that have established fixed pricing require the receipt of payment, with the exception of customers with net terms, before the commencement of any services.
- ▶ The quoted price is limited to and only covers the parts and labor for the basic service as outlined in the applicable Onboard Systems document. Any additional parts or labor needed to complete the service will be priced over and above the quoted price. The price for an exchange will be based on the quoted price plus any over and above findings or discrepancies.

Repair and Overhaul Pricing

Part Number	Description	ATP	Inspection	Overhaul	Price for New
Belly Cargo Hooks					
528-002-XX	6,000 LB Cargo Hook	\$125 USD	\$400 USD	\$2,730 USD	N/A
528-010-XX	TALON [®] LC Cargo Hook	\$125 USD	\$315 USD	\$950 USD	\$4,740 USD
528-017-XX	TALON Big Mouth Cargo Hook	\$125 USD	\$315 USD	\$1,040 USD	\$4,835 USD
528-020-XX	TALON MC Cargo Hook	\$125 USD	\$315 USD	\$1,050 USD	\$7,590 USD
528-023-XX	TALON LC Keeperless Cargo Hook	\$125 USD	\$315 USD	\$905 USD	\$5,005 USD
528-028-XX	TALON LC Hydraulic Cargo Hook	\$125 USD	\$315 USD	\$1,020 USD	\$5,270 USD
528-029-XX	TALON LC Keeperless Cargo Hook	\$125 USD	\$315 USD	\$1,020 USD	\$5,140 USD
Remote Equipment					
210-242-00	2K Remote Hook	\$165 USD	\$355 USD	\$790 USD	\$2,374 USD
210-303-00	2K Remote Hook	\$165 USD	\$355 USD	\$790 USD	\$2,375 USD
528-018-XX	3K Remote Hook	\$165 USD	\$355 USD	\$820 USD	\$2,720 USD
528-019-XX	6K Remote Hook	\$165 USD	\$355 USD	\$870 USD	\$3,790 USD
528-021-XX	2K Carousel Hook	\$125 USD	\$255 USD	\$655 USD	\$2,260 USD
210-253-00	Crew-Loc Hook Half-Cage	\$125 USD	\$255 USD	\$410 USD	\$1,530 USD
210-254-00	Crew-Loc Hook Full-Cage	\$125 USD	\$255 USD	\$410 USD	\$1,615 USD
210-302-00	Crew-Loc Hook Full-Cage	\$125 USD	\$255 USD	\$410 USD	\$1,575 USD
232-457-XX	Electrical Swivel Assembly	N/A	N/A	\$425 USD	\$1,571 USD

2017 Repair Department Pricing

Repair and Overhaul Pricing

Part Number	Description	ATP	Inspection	Overhaul	Price for New
Hook Kits					
232-289-00	Leonardo A109 Suspension System	N/A	N/A	\$2,565 USD	N/A
200-088-03	Bell 204-412 System	\$250 USD	N/A	\$6,370 USD	\$22,135 USD
200-088-10	Bell 204-412 System	\$250 USD	N/A	\$4,690 USD	\$22,135 USD
200-089-03	Bell 204-412 System w/Load Cell	\$440 USD	N/A	\$6,895 USD	\$22,135 USD
200-089-11	Bell 204-412 System w/Load Cell	\$340 USD	N/A	\$5,210 USD	\$24,255 USD
200-089-22	Bell 204-412 System w/ OWS	\$440 USD	N/A	\$5,210 USD	\$26,745 USD
200-258-XX	Bell 206L/407 Cargo Hook Kit	N/A	N/A	\$2,180 USD	\$18,720 USD
200-259-XX	Bell 206L/407 Cargo Hook Kit w/ OWS	N/A	N/A	\$2,565 USD	\$23,785 USD
200-268-XX	Bell 206 A&B Cargo Hook Kit	N/A	N/A	\$2,500 USD	\$11,355 USD
200-269-XX	Bell 206 A&B Cargo Hook Kit w/OWS	N/A	N/A	\$3,150 USD	\$15,850 USD
200-329-00	Bell 407 Fixed Suspension System	N/A	N/A	\$1,925 USD	\$19,985 USD
200-391-XX	Bell 204-412 Non-Rotating w/ OWS	\$250 USD	N/A	\$3,560 USD	\$21,635 USD
200-401-XX	Bell 204-412 Non-Rotating System	\$250 USD	N/A	\$3,050 USD	\$17,415 USD
210-164-00	Bell 206B Adaptor Link Assembly	N/A	N/A	\$165 USD	\$370 USD
232-449-01	MD500 Attach Point Assembly	N/A	N/A	\$165 USD	\$1,445 USD
232-292-01	R44 Suspension Assembly	N/A	N/A	\$165 USD	\$1,461 USD
Onboard Weighing Systems					
Misc.	Link Load Cell	\$125 USD	N/A	\$650 USD	Varies
Misc.	Shear Beam Load Cell	\$125 USD	N/A	\$1,090 USD	Varies
Misc.	Tubular Load Cell	\$150 USD	N/A	\$1,500 USD	
210-095-XX	C-39 Cockpit Indicator	\$125 USD	N/A	N/A	Varies

Upgrade Pricing

Part Number	Description	Parts Only	Parts + Factory Installation	Parts + Factory Overhaul (Free Upgrade Installation)
528-020-XX	Bell 204-412 Cargo Hook Release Lever Upgrade Kit	\$746 USD	\$896 USD	\$1,796 USD
528-020-XX	Bell 204-412 Surefire Upgrade	\$550 USD	\$695 USD	\$1,600 USD
528-028-XX	TALON LC Hydraulic Hook Surefire Upgrade	\$430 USD	\$580 USD	\$1,450 USD
528-029-XX	TALON LC Keeperless Hook Surefire Upgrade	\$430 USD	\$580 USD	\$1,450 USD

2017 Repair Department Pricing

Rental Pricing

Part Number	Description	ATP	Rental (week)	Notes
Onboard Weighing Systems				
210-095-XX	C-39 Cockpit Indicator	\$125 USD	\$120 USD	Rental plus ATP charge
210-180-XX	Analog Slave Meter	\$125 USD	\$90 USD	Rental plus ATP charge
210-048-00	C-20 Data Recorder	\$125 USD	\$195 USD	Rental plus ATP charge
210-189-00	C-30 Data Recorder	\$195 USD	\$195 USD	Rental plus ATP charge
Crophawk				
210-063-00	7 Indicator	\$125 USD	\$100 USD	Rental plus ATP charge
210-124-00	7/B Indicator	\$125 USD	\$100 USD	Rental plus ATP charge

Service Bulletin Compliance Pricing

Document Number	Description	Parts	Labor	Total	Required Part Numbers
159-001-00	Talon LC Hook Drain Holes	N/A	\$100.00 USD	\$100.00 USD	
159-002-00	Bell 204-412 Suspension Load Link	\$509.75 USD	\$50.00 USD	\$559.75 USD	232-009-01
159-003-00	TALON MC Hook Load Ring Decal	\$10.01 USD	N/A	\$10.01 USD	215-096-01
159-004-00	E-72 Release Cable	\$852.30 USD	N/A	\$852.30 USD	268-004-01, 270-085-00
159-005-02	TALON MC Hook Spring	\$20.53 USD	\$100.00 USD	\$120.53 USD	650-069-00
159-006-00	Analog Slave Meter Installation	N/A	N/A	N/A	
159-007-00	TALON LC Hook Side Plates	\$938.06 USD	\$150.00 USD	\$1,088.06 USD	232-026-02
159-009-00	Superseded by 159-020-00	N/A	N/A	N/A	
159-010-00	TALON MC Keeperless Hook Release Lever	\$512.01 USD	\$150.00 USD	\$662.01 USD	
159-011-00	TALON LC Keeperless Hook Spring	\$83.67 USD	\$100.00 USD	\$183.67 USD	
159-012-00	TALON LC Keeperless Hook Spring	\$62.04 USD	\$100.00 USD	\$162.04 USD	514-057-00, 290-819-00, 510-115-00
159-013-00	AS350 Swing Frame	N/A	N/A	N/A	
159-014-00	AS350 Swing Frame	\$7,969.27 USD	N/A	\$7,969.27 USD	210-218-00
159-015-00	R22/R44 Cargo Hook Gimbal	N/A	N/A	N/A	
159-016-00	Superseded by 159-023-00	N/A	N/A	N/A	
159-017-00	TALON LC Hook Toggle	\$457.35 USD	\$200.00 USD	\$657.35 USD	232-028-01, 290-306-01, 290-304-01

2017 Repair Department Pricing

Service Bulletin Compliance Pricing

Document Number	Description	Parts	Labor	Total	Required Part Numbers
159-018-00	TALON LC Big Mouth Release Knob	\$173.82 USD	\$50.00 USD	\$223.82 USD	290-471-02, 510-271-00, 510-246-00
159-019-00	TALON LC Hook Toggle	\$457.35 USD	\$200.00 USD	\$657.35 USD	232-028-01, 290-306-01, 290-304-01
159-020-00	Bell 206L/407 Pillow Blocks	\$2,501.32 USD	N/A	\$2,501.32 USD	232-030-02: Qty 2
159-021-00	AS350B3 Collective Friction Knob	\$350.23 USD	N/A	\$350.23 USD	291-105-00, 290-811-01
159-022-00	R44 Revised Maintenance Criteria	N/A	N/A	N/A	
159-023-00	R44 Cargo Hook Suspension	\$1,461.23 USD	N/A	\$1,461.23 USD	232-292-01
159-024-00	TALON 3K Remote Hook Keeper Bolt	\$59.90 USD	\$150.00 USD	\$209.90 USD	510-714-00, 510-239-00, 510-370-00, 514-014-00, 510-715-00, 291-277-00
159-025-00	TALON LC Keeperless Hook Locked Indication	N/A	N/A	N/A	
159-026-00	TALON LC Keeperless Hook Release Cover	\$375.50 USD	\$25.00 USD	\$400.50 USD	P/N 290-898-01
159-027-00	TALON Keeperless Hook Rigging	N/A	N/A	N/A	
159-028-00	R22/R44 12VDC Upgrade	\$355.57 USD	\$100.00 USD	\$455.57 USD	455-007-00, 340-035-00, 215-181-00, 514-056-00
159-029-00	TALON 3K Remote Hook Load Ring Size	\$11.24 USD	N/A	\$11.24 USD	215-203-00
159-030-00	Bell 206L/407 Manual Release Cable	\$632.83 USD	N/A	\$632.83 USD	268-004-01
159-033-00	Electric Swivel Operation	N/A	\$0	\$0	No labor charge for service
159-034-00	Fuel Drain Guard	\$398.73 USD	N/A	\$398.73 USD	290-899-01 & 610-024-00
159-036-00	Load Cell Torsion	\$895.00 USD	N/A	\$895.00 USD	See Service Bulletin
159-038-00	Hayabusa Hook Keeper Lock	N/A	N/A	N/A	291-722-01
159-039-00	AS350 Replacement Cargo Hook Kit manual release cable and bumper upgrade	\$2,257.29 USD	N/A	\$2,257.29 USD	268-024-02, 232-155-00

Record of Revisions

Date	Revision No.	Updates
	0	Initial release
11/15/2012	1	Added 200-258-xx, 200-259-xx, 200-329-00, and removed "Internal Use Only"
1/7/2013	2	Updated pricing for 2013 & rev'd to 2
2/14/2013	3	Updated pricing, removed Exchange option, combined content in rental price list (165-005-00) into this document, and rev'd to 3
3/29/2013	4	Added SB Compliance pricing, corrected P/N in Repair/Overhaul Pricing
6/25/2013	5	Added Onboard Weighing Systems section
1/7/2015	8	Updated all for annual price change
3/10/2015	9	Added SB 159-034-00
1/2016	10	Updated all for annual price change
5/26/2016	11	Added: 159-036-00, 159-038-00, 232-457-XX, 232-289-00, 232-292-01, 210-164-00, 232-449-01, 200-391-XX, 200-401-XX
10/13/2016	12	Added new service bulletin part information, 159-039-00
1/6/2017	13	Updated all for annual price change
6/26/2017	14	Added Surefire services, plus new Crew-Loc and 2K Remote Hook services, Bell 206 A&B services, Tubular and Shear Beam load cell services, and Update Services section.